

HOME INSPECTION REPORT Prepared Exclusively For:

, , ,



Inspected by Paul DeRick, Lic.#: 25735 on 10/23/2022 Phone: (281)744-5036, Email: derickhmins@outlook.com Website: www.derickhomeinspection.com,



PROPERTY INSPECTION REPORT FORM

Name of Client	10/23/2022 Date of Inspection
Address of Inspected Property	
Paul DeRick Name of Inspector	25735 TREC License #
Name of Sponsor (if applicable)	TREC License #

PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. *It is important* that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

RESPONSIBILITY OF THE INSPECTOR

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

RESPONSIBILITY OF THE CLIENT

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

REPORT LIMITATIONS

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices and arc-fault devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

NOTICE: THIS REPORT IS PAID FOR BY AND PREPARED FOR THE CLIENT NAMED ABOVE EXCLUSIVELY. THIS REPORT IS NOT VALID WITHOUT THE SIGNED INSPECTION AGREEMENT AND IS NOT TRANSFERABLE.

The inspection report provided by COMPANY NAME will contain the good faith opinions of the inspector concerning the observable need, if any, on the day of the inspection, for the repair, replacement, or further evaluation by experts of the items inspected. A home inspection is not an exhausting report of defects.

Unless, specifically stated, this report will not include and should not be read to indicated opinions as to the environmental conditions such as the presence of mold, radon or lead base paint, the presence of toxic or hazardous waste or substances, presence of termite or wood-destroying organisms, or compliance with codes, ordinances, statutes or restrictions, or the insurability, efficiency, quality, durability, future life, or future performance of any item inspected. This report is good for the day of the inspection only and is not to be used for Real Estate Disclosure Documents, Home Warranties or Insurance Underwriting purposes.

There are many factors which determine the life expectancy of a system or component. It is not possible to determine these factors during a one time visual inspection. Some systems of components may perform beyond their typical life expectancy while others may require repair or replacement sooner.

This report is prepared using a computer and infrequently a word or sentence may be accidentally deleted or altered. Should you encounter such a condition, please contact COMPANY NAME to make the necessary correction and provide you with replacement pages. If you do not understand certain comments or recommendations please call COMPANY NAME prior to closing on your transaction for clarification.

All items to be inspected must be accessible at the time of the inspection. Locked and or inaccessible components will not be inspected. As stated in the inspection agreement, notices sent prior to the inspection and the current Texas Real Estate Commission Texas Standards of Practice, the inspector is to inspect listed items which are visible and accessible at the time of the inspection. A re-inspection fee will apply for return trips to inspect inaccessible items.

Whenever a defect (deficiency) of any kind is noted in a system or aspect of the house, we recommend that a qualified (licensed) technician inspect and service the entire system. Sometimes noted defects are symptoms of other, sometimes more serious, defects. It is also recommended that the buyer walks through the property the day before closing to assure conditions have not changed since inspection. All items listed in the home inspection report are inspected according to today's <u>Texas Standards of Practice</u> and the most current local building standards.

NOTE: When repairs are made by certified, licensed specialists, sometimes additional defects and repair needs are discovered that were beyond the scope of a home inspection.

This report contains technical information. You are encouraged to read and understand the entire inspection report. If you do not understand or are unclear about any of the information in the report, please call COMPANY NAME (PHONE #) for a verbal consultation and report review.

INACCESSIBLE OR OBSTRUCTED AREAS

Sub Flooring - Viewed From Accessible Areas	Attic Space is Limited - Viewed from Accessible Areas
Covered Floors / Subfloors	Crawl Space is limited - Viewed From Accessible Areas
Walls/Ceilings Covered or Freshly Painted	Plumbing Areas - Only Visible Plumbing Inspected
Behind/Under Furniture and/or Stored Items	Siding Over Older Existing Siding

- **MOLD/MILDEW** investigations are NOT included with this report; it is beyond the scope of this inspection. Any reference of water intrusion is recommended that a professional investigation be obtained.
- If the property has been **RENOVATED OR REMODELED**, you should request documentation that should include permits and any warranties or guarantees that might be applicable, latent defects could exist.
- **IF ADDITIONS** have been made to this property, you should request documentation that should include permits and any warranties or guarantees that might be applicable. Latent defects could exist.
- **SELLERS DISCLOSURE.** The client is encouraged to obtain as much information about the property as possible from the Sellers Disclosure, other documents or warranties prior to closing.
- Repair technicians may find additional defects that were not included in this report. A Home Inspection is not an exhaustive list of repair needs, local building standards or deficiencies. Repair technicians may disassemble equipment or components outside the home inspectors scope as required by the Texas Standards of Practice.
- Repair technicians and their associated companies are responsible for all performance, defects, compliance with local building standards and warranties for repaired systems, appliances and components. The buyer is encouraged to obtain receipts and written transferable warranties from all repair companies prior to closing.
- If the home was occupied and or staged household goods and or furnishings limit the visible areas of walls and may conceal damage or defects that would otherwise be observed by the inspector.

☐ This report was prepared for a buyer, seller or property owner in accordance with the client's requirements. The
report addresses a single system, component or thermal imaging and is not intended as a substitute for a
complete standard inspection of the property. Standard inspections performed by a license holder and reported
on a Texas Real Estate Commission promulgated report form may contain additional information a buyer should
consider in making a decision to purchase.

Additional Notes Provided By The Inspector:

Report Identification	Report Identification: EXAMPLE-02, , ,					
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient			
I NI NP D						
	A. Foundations	I. STRUCTURAL SY	STEMS			

Foundation Type: Monolithic

Comments:

Future performance of the structure cannot be predicted or warranted. This inspection is one of first impressions and the inspector was not provided with any historical information pertaining to the structural integrity of the inspected real property. This is a limited cursory and visual survey of the accessible general conditions and circumstances present at the time of this inspection. Opinions are based on general observations made without the use of specialized tools or procedures unless otherwise noted. Therefore, the opinions are based on general apparent conditions and not of absolute fact and are only good for the date and time of this inspection. Weather conditions, drainage, leakage and other adverse factors are able to effect structures, and differential movements are likely to occur. The inspectors opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. The inspection of the foundation may show it to be providing adequate support for the structure or having movement typical to this region at the time of the inspection. This does not guarantee the future life or failure of the foundation. The inspector is not a structural engineer. This inspection is not an engineering report or evaluation and should not be considered one, either expressed or implied. If any cause of concern is noted on this report, or if you want further evaluation, you should consider an evaluation by a Structural Engineer or your choice. Foundations are inspected according to today's Texas Standards of Practice.

SUGGESTED FOUNDATION MAINTENANCE & CARE. Proper drainage and moisture maintenance to all types of foundations due to the expansive nature of the area load bearing soils. Drainage must be directed away from all sides of the foundation with grade slopes. In most cases, floor coverings and/or stored articles prevent recognition of signs of settlement and cracking in all but the most severe cases. It is important to note, this was not a structural engineering survey nor was any specialized testing done of any sub-slab plumbing systems during this limited visual inspection, as these are specialized processes requiring excavation. In the event that structural movement is noted, client is advised to consult with a Structural Engineer who can isolate and identify causes, and determine what corrective steps, if any, should be considered to either correct and/or stop structural movement.

PERFORMANCE OPINION:

☑ **Special Limitation:** Areas of the foundation perimeter beam were concealed and were not inspected. The buyer is encouraged to consult with a foundation specialist prior to closing if any concerns exist about the current or future foundation performance. Based on visual observations of other structural components at the time of the inspection, the inspector's opinion of the foundation performance is:

Deficiencies:

☑ Cracks in the foundation perimeter beam were observed but did not show indications of movement or deflection and appeared to be stress fractures. Small cracks in the foundation perimeter beam should be closely monitored over time for indications of movement, settlement, deflection, separation, or adverse performance.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





B. Grading and Drainage

Comments:

☑ The grading and drainage was inspected according to today's Texas Standards of Practice.

NOTE: Grading and drainage defects should be repaired by qualified landscape, lot drainage or rain gutter specialists.





NI=Not Inspected

NP=Not Present

D=Deficient


NI NP D



 $\ensuremath{\square}$ The gutters and downspouts contained debris that may prevent adequate drainage and create conducive conditions for water damage.







☑ □ □ ☑ C. Roof Covering Materials

Comments:

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

Type(s) of Roof Covering Materials: Composition

Viewed From: Roof Level

☑ The roof covering materials were inspected according to today's Texas Standards of Practice.

NOTE: Life expectancy of the roofing material is not covered by this home inspection report. If any concerns exist about the roof covering life expectancy or potential for future problems, a roofing specialist should be consulted. This inspection does not determine the insurability of the roof. You are strongly encouraged to have your insurance company and a roof covering specialist physically inspect the roof prior to closing to fully evaluate the condition and insurability of the roof. Roof covering materials are inspected according to current Texas Real Estate Commission Texas Standards of Practice.

NOTE: The inspection of the roof does not preclude the possibility of leakage or water damage. Leakage or water damage can occur at any time and may depend on rain intensity, wind velocity and direction and other environmental factors. The entire underside of the roof sheathing is not visible or accessible and can not be inspected for indications of leaks.

NOTE: The roof covering materials should be professionally inspected annually and after storms as part of a routine maintenance plan.

NOTE: If roof covering defects are listed below you are encouraged to have your insurance company and a certified, licensed roofing contractor to physically inspect the roof, prior to closing, to fully evaluate the insurability and condition of the roofing material.

NOTE: If the buyer has any remaining concerns about the roof covering materials, the inspector recommends that a roof covering specialist be consulted.

NOTE: Roof covering defects should be repaired or replaced as needed by a qualified roof covering specialist.

☑ The roof covering materials appeared to have reached the end of their serviceable life expectancy. The roof covering is in need of replacement or extensive repairs and a certified roof covering specialist should be consulted.

☑ Previous repairs to the roofing covering materials and/or flashings were observed. Previous repairs should be closely monitored for defects.





NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

☑ Composition shingle tab granules were observed to be thinning on the roof covering and were an indication of age, wear or other defects.

☑ Discoloration of the roof covering materials was observed and was an indication of age, wear or other defects.

☑ Roof covering shingles that do not lay flat on the roof deck were observed.









NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





☑ Areas of the roof covering drip edge flashing were damaged or improperly installed and may allow water intrusion or water damage.

 $\ensuremath{\square}$ Debris were observed on the roof covering and may contribute to roof covering material damage and water penetration.





D. Roof Structures and Attics

Comments:

Attic Space Viewed From: Entered the Attic

Approximate Visible Attic Space: 40-60 Percent Visible

Average Depth of Insulation: 4-8 Inches

 $\ensuremath{\square}$ The roof roof structure and attic were inspected according to today's Texas Standards of Practice.

NOTE: There were household goods, stored items or debris in the attic that limit the visible areas of the attic and may conceal damage or defects that would otherwise be observed.

NOTE: Attic access defects should be repaired by qualified specialists.

☑ Damaged attic access ladders may not provide adequate support and were observed to be a

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

SAFETY HAZARD.



☑ Insulation voids were observed in the attic space and may allow greater than normal loss of conditioned air.


Comments:

☑ The walls were inspected according to today's Texas Standards of Practice.

NOTE: Exterior wall repairs should be made by a qualified repair specialist.

 $\ensuremath{\square}$ The exterior wood trim was observed to have some deterioration, wood rot and/or water damage.





NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





✓				F.	Ceilings	and	Floors
---	--	--	--	----	-----------------	-----	---------------

Comments:

☑ The ceilings and floors were inspected according to today's Texas Standards of Practice.

\square \square \square \square \square G. Doors (Interior and Exterior)

Comments:

☑ The doors were inspected according to today's Texas Standards of Practice.

NOTE: Door repairs should be made by a qualified repair specialist.

Interior Doors:

☑ All interior doors should have door stops installed to prevent damage to adjacent interior wall coverings.

Exterior Doors:

One exterior door could not open all the way due to deflection of the rear porch slab.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D







- ☑ One or more dead-bolt locks did not engage the door frame as intended and may not fully lock (SAFETY HAZARD).
- ☑ Deficient hardware at exterior doors was observed.
- ☑ Damaged or missing exterior door weather stripping was observed and may allow moisture intrusion and conditioned air loss.
- ☑ Safety glass was not installed in exterior doors in required locations and was observed to be a SAFETY HAZARD.
- ☑ Exterior doors that rub, stick or hit door frames were observed and may be an indications of movement, settlement, adverse structural performance or other defects.
- ☑ Garage entry doors should have installed self closing hinges according to current building standards.
- ☑ The garage entry door was observed to be a non-fire rated door under current building standards (SAFETY HAZARD).

I =]	I=Inspected				NI=Not Inspected	NP=Not Present	D=Deficient
I	NI	NP	D				
\square				Н.	Windows Comments:		
					☑ The windows were insp	ected according to today's	Texas Standards of Practice.
	V			I.	Stairways (Interior and Ex Comments:	terior)	
		V		J.	Fireplaces and Chimneys Comments:		
				K.	Porches, Balconies, Decks, Comments:	and Carports	
					☑ The porches, decks, ba Standards of Practice.	llconies and carports were i	nspected according to today's Texas
					☑ The wood deck concea foundation in this area.	ls the foundation or brick led	dge and prevents visual inspection of the

☑ Weathered, deteriorated and/or damaged wood deck materials were observed.



 $\ \square$ Deck and patio cover ledge board should not be supported by brick or stone masonry according to current building standards.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



L. Other

Comments:

☑ The flatwork was inspected according to today's Texas Standards of Practice.

☑ Differential movement of the flatwork such as garage floors, driveways, walkways, patios or steps was observed and may be an indication of movement, settlement or other defects.



II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels

Comments:

Electric Service Panel Location: Rear Exterior Wall

☑ The electric service panel and entrance was inspected according to today's Texas Standards of Practice.

Deficiencies:


NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

☑ Sub-Panel grounds and neutrals were installed on the same bus bar. Although the sub-panel may be functional, it does not meet current National Electrical Code standards.



B. Branch Circuits, Connected Devices, and Fixtures

Comments:

Type(s) of Visible Branch Circuit Electrical Conductors: Copper

☑ The branch circuits, connected devices and fixtures were inspected according to today's Texas Standards of Practice.

NOTE: Electric branch circuit and connected device repairs should be made by a licensed electrician.

NOTE: Electrical components concealed behind finished surfaces or under insulation are not inspected. The inspection does not include remote control devices, alarm systems, low voltage wiring, ancillary wiring or intercoms.

NOTE: It is recommended to replace smoke and fire alarm batteries with each change of ownership and once annually for reasons of safety. Replacement of smoke and fire alarms older than 10 years is recommended.

☑ The exterior HVAC equipment electrical disconnect was installed behind the outside condenser/coil and does not meet the clearance requirements of the National Electrical Code (SAFETY HAZARD).

☑ Mismatched breaker sizes between the exterior cooling equipment (Max/Min Amperage), disconnect and/or the electric service panel breaker were observed.

☑ The exterior electrical service disconnect box for the outside cooling equipment was weathered, rusted.

NI=Not Inspected

NP=Not Present


D=Deficient

NI NP D



Arc-Fault Protection (AFCI) & Ground Fault Circuit Interruption Protection (GFCI)

☑ Dual function breakers that provide both AFCI and GFCI protection are now available and became a National Electric Code (NEC) building standard in 2014. Under current electrical standards, AFCI protection is now required in family rooms, dinning rooms, living rooms, parlors, libraries, dens, bedrooms, sun rooms, recreation rooms, closets, hallways, kitchens and laundry rooms. Lack of AFCI protection in required locations is a SAFETY HAZARD.



Smoke, Fire Alarms And Carbon Monoxide Detectors:

☑ Smoke alarms were not installed in required locations (SAFETY HAZARD). Under current building standards, there should be a smoke alarm located in each sleeping room, outside each separate sleeping area in the immediate vicinity of the sleeping rooms, and on each additional story of the dwelling, including basements but excluding crawl spaces and uninhabitable attics (in dwellings with split levels and without an intervening door between the levels, a smoke alarm installed on the upper level and the adjacent lower level shall suffice provided that the lower level is less than one full story below the upper level).

☑ An audible sound was heard from the smoke detectors, indicating that the batteries need to be changed (SAFETY HAZARD). It is recommended to replace the batteries in all of the smoke detectors once a year for reasons of safety.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	vehicle storage area (sleeping areas and at	garage) should have installe each story. Lack of a carbo	th gas fired appliances and or an attached ed carbon monoxide detectors outside of all n monoxide detectors in required locations is a exide detectors older than 10 years is
	C. Other Comments:		
	NOTE: Low voltage e home inspection and		ntertainment wiring are outside the scope of this
	III. HEATING, VE	NTILATION AND AIR	CONDITIONING SYSTEMS
	A. Heating Equipment Comments:		
	Type of Heating Sys Heating Energy Sou	tem: Forced Air / Central	
	The Gas Utility was tu	rned off at the time of inspe	ction.
	☑ The heating equipn	nent was inspected accordir	ng to today's Texas Standards of Practice.
	the HVAC and related HVAC specialist. The the HVAC electrical sy accessible without operation as heat exchangers, concerning to pressure. No guarante evaporator coil, plenucan be made regarding expectancy. Inspection most heating equipments home inspection. No guarante expectancy.	equipment may benefit from scope of our inspection includes a protected cabinet or coils or air handlers. We do not see is made regarding coolar mand air handler are outsing evaporator coils, cooling I not the heat exchanger is not systems. Inspection of the guarantee can be made on the scope of the systems.	and cooling system inspection is to determine of a more thorough inspection by a qualified udes but is not limited to a visual inspection of oils, gas burners, filters and thermostats (if shroud). We do not dismantle components such that the formold, refrigerant leaks or adequate at charge or line integrity. The condition of the lethe scope of a home inspection. No guaranterines, plenums, air handlers or component life not possible without disassembly of the unit in the heat exchanger is beyond the scope of a she heat exchangers life expectancy. If concerns intractor further evaluate the HVAC system prior
			nished grade (underground) or between the detected and are not inspected.
	NOTE: Heating aguin	mont or hoot nump could be	at he energted or inspected for performance due

NOTE: Heating equipment or heat pump could not be operated or inspected for performance due to outside air temperature being greater than 70 degrees Fahrenheit at the time of inspection. Operation at or above 70 degrees could cause damage to the unit. Inspection of the heating equipment was limited to visual observation.

Deficiencies:

☑ Heating equipment was inoperative. Gas Utility was turned off.

report recommends	<u> </u>			
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	B. Cooling Equipment Comments:			

Cooling Equipment Type: Central - Air Conditioner

Report Identification: **EXAMPLE-02**

☑ The cooling equipment was inspected according to today's Texas Standards of Practice.

NOTE: The objective of our limited visual heating and cooling system inspection is to determine of the HVAC and related equipment may benefit from a more thorough inspection by a qualified HVAC specialist. The scope of our inspection includes but is not limited to a visual inspection of the HVAC external electrical system, fan, compressor, coils, filters and thermostats (if accessible without opening a protected cabinet or shroud). We do not dismantle components such as heat plenums, air handlers or coils. We do not test for refrigerant leaks or adequate pressure. No guarantee is made regarding coolant charge, line integrity, plenums or air handlers. The condition of the evaporator coil, plenum and air handler are outside the scope of a home inspection. No guarantee can be made regarding coils, cooling lines, plenums, air handlers or component life expectancy. If concerns exist, it is highly recommended that a qualified contractor further evaluate the HVAC system prior to closing.

 $\ensuremath{\square}$ The exterior electrical service disconnect box for the outside cooling equipment was weathered, rusted or damaged.



C.	Duct Systems, Chases, and Vents Comments:
	$\ \square$ The duct systems, chases and vents were inspected according to today's Texas Standards of Practice.
D.	Other Comments:
A.	IV. PLUMBING SYSTEMS Plumbing Supply, Distribution Systems and Fixtures Comments:

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

Location Of Water Meter: Front Yard

Location Of Main Water Valve: Right/Front Exterior Wall

Static Water Pressure: 45-50 psi

Type of supply piping material: Galvanized - SAFETY HAZARD

Visible Water Pressure Valve/Regulator: No


☑ The plumbing supply, distribution and fixtures were inspected according to today's Texas Standards of Practice.

NOTE: Slab construction prevents visual inspection of plumbing located in or below concrete slabs. Plumbing concealed in foundations, below grade, under flatwork, under decks, inside walls, in attics, between ceilings, insulated, in crawl spaces or concealed by other finishes are outside the scope of a home inspection and were not inspected.

NOTE: Structural movement, settlement or previous foundation repairs can lead to latent plumbing defects that may not be revealed during a home inspection. If any plumbing defects, structural movement, settlement or previous foundation repairs have been reported, the buyer is encouraged to have the plumbing systems further evaluated and a hydrostatic water pressure test performed by a certified, licensed plumbing specialist.

NOTE: The inspector has no way of knowing the water usage history of the structure. The buyer is encouraged to obtain water usage history before closing to determine if water leaks in the main water supply system are present.

☑ Exterior water supply faucets were missing an anti-siphon device to prevent contaminants from entering the water supply (SAFETY HAZARD).



☑ Toilet water runs indicating that repairs are needed.

☑ The temperature indicators were missing at the tub/shower water supply fixture (SAFETY HAZARD).

☑ The tub/shower water supply fixtures lacked adequate sealant at the wall.

B. Drains, Wastes, and Vents

Comments:

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

Type of drain piping material: PVC
Waste Drain Clean Out Location: Not Located

☑ The drains, wastes and vents were inspected according to today's Texas Standards of Practice.

NOTE: Slab construction prevents visual inspection of waste drain plumbing located in or below concrete slabs. Waste drain plumbing concealed in foundations, below grade, under flatwork, under decks, inside walls, in attics, between ceilings, insulated, in crawl spaces or concealed by other finishes are outside the scope of a home inspection and were not inspected.

NOTE: Only a video scan of the interior of drain pipes and drain lines can fully confirm their actual condition. The inspector has no way of knowing about waste drain leaks or the history of waste drain leaks in concealed areas or latent conditions. When the house has been vacant, the plumbing system is older, there are prior known drain problems, large trees on the grounds or non-disclosed wast drain defects, it would be prudent to have the drain lines "video scanned" prior to closing.

NOTE: Structural movement, settlement or previous foundation repairs can lead to latent waste drain defects that may not be revealed during a home inspection. If any waste drain defects, structural movement, settlement or previous foundation repairs have been reported, the buyer is encouraged to have the waste drain plumbing further evaluated by a certified, licensed plumbing specialist.

☑ Inadequate materials such as accordion type plumbing were used as waste drain plumbing.





☑ Waste drains were slow to drain at sinks or tubs.

☑ □ □ ☑ C. Water Heating Equipment Comments:

Water Heater Energy Source: Gas Water Heater Capacity: 40 Gallons Water Heater Location: Garage Expansion Tank Present: No

Measured Heated Water Temperature: °F

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

The Gas Utility was turned off at the time of inspection.

- ☑ The water heating equipment was inspected according to today's Texas Standards of Practice.
- ☑ The water heating equipment was inoperative.
- ☑ The water heating equipment overflow pan lacks a drain to the exterior of the structure.



☑ Gas flue/vent is loose, damaged, improperly installed or poorly connected at water heating equipment (SAFETY HAZARD).



☑ The water heating equipment TPR drain line was not plumbed to the exterior.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



✓	✓	D.	Hydro-Massage Therapy Equipment Comments:
		Е.	Gas Distribution Systems and Gas Appliances <i>Comments</i> :

Gas Meter Location: Back Of Structure

Visible Material For Gas Supply Plumbing: Black Iron Pipe

SPECIFIC LIMITATIONS: The Inspector is not required to inspect sacrificial anode bonding or for its existence. The Inspector does not perform a pressure test on the gas lines. The Inspector cannot detect gas leaks below the finished grade (underground) or between the wall or behind fireplace hearths or any concealed area. **Propane tanks will not be inspected.** If any further concerns exist about possible gas line failure and or deficiencies, we recommend that the buyer, seller or agent have the gas system further evaluated by a local controlling gas supplier and or a certified, licensed master plumber.

☐ ☑ ☐ ☐ F. Other Comments:

NOTE: If a fire suppression system is installed, fire suppression systems are outside the permitted license of inspection for a home inspector. Fire suppression systems, inspection, repair and evaluation should be performed by a certified, licensed Texas Fire Marshall or Texas certified, licensed fire suppression system specialist.

NOTE: If a water treatment or water softening system installed, the adequacy and performance of water treatment and water softening systems is outside the scope of this home inspection. Water treatment or water softening systems are not inspected. Furthermore:

- The water treatment discharge point was not located or inspected. The buyer is encouraged to have all water treatment or water softening system equipment further evaluated by a certified, licensed water treatment system specialist.
- The buyer should have any/all water treatment system filters replaced prior to closing to prevent contamination, illness, decease or other defects.

_					NI Not Inspected	ND Not Duogont	D. Dofficient
	Inspe NI				NI=Not Inspected	NP=Not Present	D=Deficient
1	111	INI	D				
_	_	_	_			V. APPLIANCI	ES
	V	$\overline{\mathbf{V}}$		A.	Dishwashers Comments:		
☑				В.	Food Waste Disposers Comments:		
					☑ The food waste dispo	ser was inspected accord	ding to today's Texas Standards of Practice.
$\overline{\mathbf{V}}$				C.	Range Hood and Exhaus Comments:	t Systems	
					☑ The range hood and e Practice.	exhaust system was insp	ected according to today's Texas Standards of
	V			D.	Ranges, Cooktops, and O	vens	
					Oven Energy Source: Cooktop Energy Source		
					The Gas Utility was turned	ed off at the time of inspe	ection.
				Е.	Microwave Ovens Comments:		
V				F.	Mechanical Exhaust Ven Comments:	ts and Bathroom Heaters	
					☑ The mechanical exha Texas Standards of Prac		neaters were inspected according to today's
					NOTE: Mechanical exha	aust vents should be repa	ired by a qualified appliance specialist.
					☑ There were inoperative	ve mechanical exhaust ve	ents.

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



☑ G.	Garage Door Operators Comments:
	☑ The garage door operators were inspected according to today's Texas Standards of Practice.
	NOTE: Garage door operators should be repaired by a qualified appliance specialist.
	☑ The garage door operator was inoperative or did not perform as intended.
	$\ensuremath{\square}$ When an automatic garage door opener is installed the manual door locks should be disabled or removed.
	☑ The automatic garage door opener light/lens cover was damaged or missing.
	☑ The automatic garage door opener light was inoperative.
⊐ н.	Dryer Exhaust Systems Comments:
	☑ The dryer exhaust systems were inspected according to today's Texas Standards of Practice.
	NOTE: The National Fire Protection Association (NFPA) recommends that all dryer vent ducts be made from straight metal dryer ducts rather than plastic or flexible metal for improved safety.
	NOTE: Some clothes dryer vent duct installations are longer than normal. It is important to determined if the dryer that will be in this location has a high enough CFM (Fan Speed & Air Flow) to push lint and moisture over the required distance. The buyer is encouraged to learn more about this installation from the seller, builder and clothes dryer manufacturer.
□ I.	Other Comments:

I=	Insp	ected			NI=Not Inspected	NP=Not Present	D =Deficient	
Ι	NI	NP	D					
					elevators, lifts, automatic home inspection and if p	c gate openers and whol	compactors, washing machines, clothes e house vacuums are outside the scope were not inspected. The buyer is encou in these appliances.	of this
						VI. OPTIONAL SY	STEMS	
	$\overline{\mathbf{A}}$			A.	Landscape Irrigation (Sp. Comments:	orinkler) Systems		
					inspection is to determin a qualified specialist. The landscape irrigation system provides a narrative list not dismantle any lands automatic functions, effectives.	ne if the system would be the scope of our inspection tem controls and operation of deficiencies related to cape irrigation equipment ectiveness of sensors, effort	ape irrigation system (sprinkler system) nefit from inspection, improvements or real includes a limited visual inspection of the or of the system in manual mode. The insperformance, installation and operation. It or program the system. Effective coverage ctiveness of backflow prevention and the scope of this inspection and are not inspection.	ne spection We do age, ne
				В.	Swimming Pools, Spas, F Comments:	Iot Tubs, and Equipment		
					equipment would benefit and spa specialist. The system, circulation system components. Water che equipment, control valve pool/spa covers, chloring outside the scope of this	t from inspection, repairs scope of our inspection in em, barriers, surfaces an mistry is not evaluated. Ves, chemical injectors or ators, chemical dispense	ad spa equipment inspection is to determ or improvements by a certified, licensed includes a limited visual inspection of elected decking. We do not dismantle pool and We do not inspect or operate heaters, clesimilar components. Pool/spa computer ors, conditioners, and water ionization developments. Pools, spas, hot tubs and equipments of Practice.	pool etrical spa aning controls, vices are
	V			C.	Outbuildings Comments:			
				D.	Private Water Wells (A c Comments:	coliform analysis is recom	mended)	
					Type of Pump: Water F Type of Storage Equip Proximity to Septic Sy	ment: Water Storage Ed	<u>uipment</u>	
	V			Е.	Private Sewage Disposal Comments:	Systems		
					Type of Septic System	: <u>Septic Systems</u>		
					Inspected By: Paul Del	51.1		

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

System Age:

Bedrooms: # of Units
Bathrooms: # of Units

Drain Or Distribution Field Location:

Tanks Recently Pumped: Yes/No

Tanks Accessible: <u>Yes/No</u> Sludge Measured: <u>Yes/No</u>

Date Pumped:

Measurements:

Septic System Performance:

☑ There was standing water, seepage or overflow visible at the septic system tanks, sprinkler heads, soil treatment field and or lateral lines (SAFETY HAZARD).

Additional Information:

NOTE: For more information about septic systems, we recommend the following websites; National Association of Waste Water Transporters, Selman Home Inspections and Texas Commission on Environmental Quality.

- 1. If property has been vacant more than a week or the system has been only minimally used, additional levels of testing and inspection by a septic system specialist may be necessary to determine system condition.
- 2. If the system has been serviced recently, contact the septic pumping company to inquire about the type and condition of the waste disposal equipment.
- 3. If the system has not been serviced recently, limited but important additional information regarding the condition of the system may be obtained by having a septic contractor open, clean, and inspect the septic tank (and distribution boxes). Particularly in the case of older systems that have not been serviced, if the property owner will permit this step we recommend it.
- 4. Excavation and pumping are beyond the scope of our operational testing procedure. Practices in some states require pumping and inspection at sale.
- 5. Septic systems are basically a "buried" installation and are hidden from normal visual inspection. Many possible problems may not show themselves at the time of a visual inspection, and thus one cannot make accurate prediction of the future condition of the system.
- 6. Determination of location, condition, or life expectancy of buried septic components is not possible from a visual inspection. Costly problems may not be visible.
- 7. Periodic pumping is recommended to prevent costly damage to the absorption system. Pumping frequency depends on system usage, tank size, and other factors.
- 8. The inspection includes visual examination of probable tank and absorption system areas, surface and perimeter, at the beginning, during, and at the end of operational testing, if such was performed.
- 9. Condition and / or type of subsurface equipment have not been inspected. If a determination of field lines is needed we recommend having a qualified, certified and licensed septic installing specialist inspect system.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	the tanks can be dug		guaranteed, without special equipmer commend having a qualified, certified a n.	
	11. Septic system performs as to the number of occupants who use the system. An increa occupants can sometime cause the system to malfunction. Consistent and regular mainter will help this prevent certain conditions. We recommend having a qualified, certified and lice septic pumping specialist inspect the system.			intenance
	12. Buyer should contact local septic controlling authorities to determine all local region concerning waste water regulation in their area.			ations
		S. testing is outside the sco licensed septic maintaining	pe of this inspection. We recommend specialist inspect system.	I having a
			with a septic system. We recommend which discharge into septic systems	
		re harmful to septic systems septic specialist inspects sy	s. We recommend consulting with a q stem about softeners.	ualified,
			septic systems. We recommend cons	
		ns are not conducted with the	is type of inspection. We recommendialist inspects system.	d consulting

18. Medicines, paints, chemicals, rubber products, feminine products and / or other nonbiodegradable material must not be put into septic systems. We recommend having a qualified, certified and licensed septic pumping specialist regularly inspect system.

WARNING: Tanks not pumped regularly are at extra risk of hidden, potentially costly damage to the absorption system. Tanks pumped immediately prior to the inspection may prevent normal system testing (by loading with water) and may indicate a history of recent problems or failures.

F. Other Built-in Appliances Comments:	
G. Re-Inspection Comments:	
	REINSPECTION OF REPAIRED ITEMS
Date:	
•	may find additional defects that were not included in this report. A

Home Inspection is not an exhaustive list of repair needs, local building standards or deficiencies. Repair technicians may disassemble equipment or components outside the home inspectors scope as required by the Texas Standards of Practice.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

NOTE: Repair technicians and their associated companies are responsible for all performance, defects, compliance with local building standards and warranties for repaired systems, appliances and components. The buyer is encouraged to obtain receipts and written transferable warranties from all repair companies prior to closing.

REINSPECTED ITEMS:

REPORT SUMMARY

The "Report Summary" section is intended to be a tool to assist our clients and their representative(s) in preparing a repair request, if and when applicable. THIS IS NOT A LIST OF MANDATORY REPAIRS BUT A LIST OF SUGGESTED REPAIRS OR UPGRADES NEEDED. The Report Summary is intended to follow the flow of the main body of the Property Inspection Report. The order of repair priority is left up to the sole discretion of the client and your Inspector will not be able to assist you specifying order of importance. Further, this summary contains only those items identified as "Deficient". There may be other items listed in the full body of the Property Inspection Report that could be important to you and you may consider adding to your repair request if and when applicable. You should read and understand the entire Home Inspection Report prior to completing any repair request. This report contains technical information, if you do not understand or are unclear about some of the information contained in the body of this report; please call the office to arrange for a verbal consultation with your inspector prior to the expiration of any time limitations such as option periods.

Items Needing Further Evaluation

- ☑ The roof covering materials appeared to have reached the end of their serviceable life expectancy. The roof covering is in need of replacement or extensive repairs and a certified roof covering specialist should be consulted.
- ☑ Previous repairs to the roofing covering materials and/or flashings were observed. Previous repairs should be closely monitored for defects.
- ☑ Discoloration of the roof covering materials was observed and was an indication of age, wear or other defects.
- ☑ Roof covering shingles that do not lay flat on the roof deck were observed.
- ☑ Exposed or lifting fasteners or nail heads were observed at the roof coverings that may allow water penetration.
- ☑ Sub-Panel grounds and neutrals were installed on the same bus bar. Although the sub-panel may be functional, it does not meet current National Electrical Code standards.
- ☑ Mismatched breaker sizes between the exterior cooling equipment (Max/Min Amperage), disconnect and/or the electric service panel breaker were observed.
- ☑ The water heating equipment was inoperative.
- ☑ The water heating equipment overflow pan lacks a drain to the exterior of the structure.
- ☑ The garage door operator was inoperative or did not perform as intended.

Home Safety

- ☑ Damaged attic access ladders may not provide adequate support and were observed to be a SAFETY HAZARD.
- ☑ One or more dead-bolt locks did not engage the door frame as intended and may not fully lock (SAFETY HAZARD).
- ☑ Safety glass was not installed in exterior doors in required locations and was observed to be a SAFETY HAZARD.
- ☑ The garage entry door was observed to be a non-fire rated door under current building standards (SAFETY HAZARD).
- ☑ The exterior HVAC equipment electrical disconnect was installed behind the outside condenser/coil and does not meet the clearance requirements of the National Electrical Code (SAFETY HAZARD).
- ☑ Dual function breakers that provide both AFCI and GFCI protection are now available and became a National Electric Code (NEC) building standard in 2014. Under current electrical standards, AFCI protection is now required in family rooms, dinning rooms, living rooms, parlors, libraries, dens, bedrooms, sun rooms, recreation rooms, closets, hallways, kitchens and laundry rooms. Lack of AFCI protection in required locations is a SAFETY HAZARD.
- ☑ Smoke alarms were not installed in required locations (SAFETY HAZARD).
- ☑ An audible sound was heard from the smoke detectors, indicating that the batteries need to be changed (SAFETY HAZARD).
- ☑ Current building standards state that homes with gas fired appliances and or an attached vehicle storage area (garage) should have installed carbon monoxide detectors outside of all sleeping areas and at each story. Lack of a carbon monoxide detectors in required locations is a SAFETY HAZARD. Replacement of carbon monoxide detectors older than 10 years is recommended.
- ☑ Exterior water supply faucets were missing an anti-siphon device to prevent contaminants from entering the water supply (SAFETY HAZARD).
- ☑ The temperature indicators were missing at the tub/shower water supply fixture (SAFETY HAZARD).
- ☑ Gas flue/vent is loose, damaged, improperly installed or poorly connected at water heating equipment (SAFETY

HAZARD).

☑ There was standing water, seepage or overflow visible at the septic system tanks, sprinkler heads, soil treatment field and or lateral lines (SAFETY HAZARD).

Repair & Maintenance Items

- ☑ The gutters and downspouts contained debris that may prevent adequate drainage and create conducive conditions for water damage.
- ☑ Areas of the roof covering drip edge flashing were damaged or improperly installed and may allow water intrusion or water damage.
- ☑ Debris were observed on the roof covering and may contribute to roof covering material damage and water penetration.
- ☑ Insulation voids were observed in the attic space and may allow greater than normal loss of conditioned air.
- ☑ The exterior wood trim was observed to have some deterioration, wood rot and/or water damage.
- ☑ All interior doors should have door stops installed to prevent damage to adjacent interior wall coverings.
- ☑ Deficient hardware at exterior doors was observed.
- ☑ Damaged or missing exterior door weather stripping was observed and may allow moisture intrusion and conditioned air loss.
- ☑ Exterior doors that rub, stick or hit door frames were observed and may be an indications of movement, settlement, adverse structural performance or other defects.
- ☑ Storm doors were observed to be damaged, missing components or did not close as intended.
- ☑ Garage entry doors should have installed self closing hinges according to current building standards.
- ☑ Weathered, deteriorated and/or damaged wood deck materials were observed.
- ☑ Deck and patio cover ledge board should not be supported by brick or stone masonry according to current building standards.
- ☑ Differential movement of the flatwork such as garage floors, driveways, walkways, patios or steps was observed and may be an indication of movement, settlement or other defects.
- ☑ The exterior HVAC equipment electrical disconnect was installed behind the outside condenser/coil and does not meet the clearance requirements of the National Electrical Code (SAFETY HAZARD)
- ☑ The exterior electrical service disconnect box for the outside cooling equipment was weathered, rusted.
- ☑ Heating equipment was inoperative.
- ☑ The exterior electrical service disconnect box for the outside cooling equipment was weathered, rusted or damaged.
- ☑ Toilet water runs indicating that repairs are needed.
- ☑ The tub/shower water supply fixtures lacked adequate sealant at the wall.
- ☑ Inadequate materials such as accordion type plumbing were used as waste drain plumbing.
- ☑ Waste drains were slow to drain at sinks or tubs.
- ☑ The water heating equipment TPR drain line was not plumbed to the exterior.
- ☑ There were inoperative mechanical exhaust vents.
- ☑ When an automatic garage door opener is installed the manual door locks should be disabled or removed.
- ☑ The automatic garage door opener light/lens cover was damaged or missing.
- ☑ The automatic garage door opener light was inoperative.

Improvement & "As Built Condition" Items

Items To Monitor

☑ Cracks in the foundation perimeter beam were observed but did not show indications of movement or deflection and appeared to be stress fractures. Small cracks in the foundation perimeter beam should be closely monitored over time for indications of movement, settlement, deflection, separation, or adverse performance.

Deferred Cost Items

If Something Goes Wrong

There may come a time when you discover something wrong with the house you purchased, and you may be upset or disappointed with your home inspection. There are some things we'd like you to keep in mind.

Intermittent Or Concealed Problems:

Some problems can only be discovered by living in a house. They cannot be discovered during the few hours of a home inspection. For example, some shower stalls leak when people are in the shower, but do not leak when you simply turn on the tap. Some roofs and basements only leak when specific conditions exist. Some problems will only be discovered when carpets are lifted, furniture is moved or finishes are removed.

No Clues:

These problems may have existed at the time of the inspection, but there were no clues as to their existence. Our inspections are based on the past performance of the house. If there are no clues of a past problem, it is often impossible for us to foresee a future problem.

We Sometimes Miss Minor Things:

During our inspection we often discover minor problems while we are looking for the more significant problems. While we try to note as many of the minor problems as we can, we concentrate on finding the more significant problems. These are the ones that affect people's decisions to purchase.

Contractor's Advice:

A common source of dissatisfaction with home inspectors comes from comments made by contractors. Contractor's opinions often differ from ours. You may have more than one roofing contractor say that the roof needs replacement, when we said that the roof would last a few more years with some minor repairs.

Last Man In Theory:

While our advice represents the most prudent thing to do, many contractors are reluctant to undertake these repairs. This is because of the last man in theory. The contractor fears that if he is the last person to work on the roof, he will get blamed if the roof leaks, regardless of whether or not the roof leak is his fault. Consequently, he won't want to do a minor repair with high liability, when he could re-roof the entire house for more money and reduce the likelihood of a callback. This is understandable.

Most Recent Advice Is Best:

There is more to the last man in theory. It suggests that it is human nature for homeowners to believe the last bit of expert advice they receive, even if it is contrary to previous advice. As home inspectors, we find ourselves in the position of first man in and consequently it is our advice that is often forgotten.

Why Didn't We See It?

You may have a contractor say, I can't believe you had this house inspected, and the inspector didn't find this problem. There are several reasons for these **apparent** oversights:

A contractor may not know what is within the scope of a Home Inspection. The scope of a Home

Inspection is very specific, and all of our inspections are conducted in accordance with the Texas Standards of Practice for Home Inspectors. The Standards of Practice are very specific as to what is included and excluded from a home inspection.

Conditions During The Inspection: The conditions during the inspection are often very different that those when while the contractor is present. It is often difficult for homeowners to remember the circumstances in the house at the time of the inspection. Weather conditions, temperature and time of day can drastically affect the way many of the home systems perform, leading to different results from the time of the inspection to the time the contractor is present in the home. It's impossible for contractors to know what the circumstances were when the inspection was performed.

The Wisdom Of Hindsight: When a problem manifests itself, it is very easy to have 20/20 hindsight, and wonder why the inspector was not able to predict a particular problem. As inspectors, we have been trained to look at all of the evidence available at the time of the inspection and give the most accurate prediction we can with the knowledge we have.

<u>A Limited Look:</u> We typically spent 3-4 hours to conduct a Home Inspection. During that limited amount of time, we cannot completely disassemble components or examine every hidden component location.

We're Generalists: We are generalists; we are not specialists. HVAC contractors, roofers, electricians, plumbers, etc may all indeed have more expertise than we do in their specific field. As inspectors, we are trained in all of the homes systems and components, and look for general conditions that may indicated the need for further evaluation by a specialist.

A Non-Invasive Look: Problems often become apparent when carpets or plaster are removed, when fixtures or cabinets are pulled out, and so on. A home inspection is a visual examination. We don't perform invasive or destructive tests.

Not Insurance:

In conclusion, a home inspection is designed to better your odds of not purchasing a "money pit". It is not designed to eliminate all risk. For that reason, a home inspection should not be considered a written guarantee or an insurance policy.